

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2020

Submitted Date:

03/18/2020

Document Number:

693502553**FIELD INSPECTION FORM**Loc ID 317649 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239689	WELL	PR	03/20/1995	GW	123-07477	ROCKY MOUNTAIN FUEL CO B 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Flow line risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with rule 603 f For unused , unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.		Date: <u>04/18/2020</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused Pumping unit and associated parts and cement base equipment appears to have been on site for some time due to equipment being burried in dirt.		
Corrective Action:	Comply with 603 f		Date: <u>04/18/2020</u>

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type			
Comment:			
Corrective Action:			Date:

Equipment:				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:			Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities

Facility ID: 239689 Type: WELL API Number: 123-07477 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday March 18, 2020 at approximately 9:06AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Rocky Mountain fuel CO B #1</p> <p>Operator: KP Kauffman</p> <p>API#:05-123-07477</p> <p>County: Weld</p> <p>While there, I observed a well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment: rule 603f Corrective action date of 4-18-20 See photo 2</p> <p>Unused Equipment: rule 603 f Corrective action date of 4-18-20 See photos 3,4</p> <p>Weather conditions: Clear and dry.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	03/18/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402347107	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100077
693502554	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100076