

FORM  
INSPRev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2020

Submitted Date:

03/20/2020

Document Number:

689803815

### FIELD INSPECTION FORM

Loc ID 447512 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10598  
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC  
Address: 123 ROBERT S KERR AVE  
City: OKLAHOMA CITY State: OK Zip: 73102

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447586	WELL	PR	02/01/2019		057-06581	Peters 0781 15-13H12	PR
447587	WELL	PR	02/01/2019		057-06582	Peters 0781 13-13H12	PR
447589	WELL	PR	02/01/2019		057-06583	Peters 0781 11-13H12	PR
447590	WELL	PR	02/01/2019		057-06584	Peters 0781 9-13H12	PR
448966	WELL	PR	04/01/2019		057-06590	Peters 0781 10-13H12	PR

**General Comment:**

Follow up FIU inspection to inspection from 10/2/2019 document number 689803160. The only corrective action remaining outstanding is the submittal of tank containment liner documents via FIRR, all other corrective actions have been resolved.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Several wellhead signs have been knocked over.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 405-429-5974

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Emission Control Device	# 5			
Comment:				
Corrective Action:		Date:		
Bird Protectors	#			
Comment:				
Corrective Action:		Date:		
Other	# 5			
Comment:	Jet pumps			
Corrective Action:		Date:		
Horizontal Separator	# 5			
Comment:				
Corrective Action:		Date:		

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Previous inspection document number 689803160 asked for evidence of compliance with Rule 605.a(4) via FIRR.			
Corrective Action:	Please provided documentation of tank liner installation via FIRR.			Date: 04/12/2019
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

<b>Inspected Facilities</b>				
Facility ID: <u>447586</u>	Type: <u>WELL</u>	API Number: <u>057-06581</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>447587</u>	Type: <u>WELL</u>	API Number: <u>057-06582</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>447589</u>	Type: <u>WELL</u>	API Number: <u>057-06583</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>447590</u>	Type: <u>WELL</u>	API Number: <u>057-06584</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>448966</u>	Type: <u>WELL</u>	API Number: <u>057-06590</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b>Producing Well</b>				
Comment:				
Corrective Action:			Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402348566	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101441">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101441</a>
689803816	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101430">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101430</a>