

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2020

Submitted Date:

03/26/2020

Document Number:

693200583

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: Murray, Richard On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:

OGCC Operator Number: 13980

Name of Operator: RED ROCK GATHERING COMPANY LLC

Address: 999 18TH STREET STE 3400 SOUTH

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Harold Rhodes		harold.rhodes@summitmidstream.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
474138	SPILL OR RELEASE	AC	03/26/2020		-	RedRock Gathering System_Premier 6"	EG

General Comment:

COGCC joint inspection with EPS J. Heil and Western Integrity Inspector R. Murray

Engineering Integrity Inspection performed on February 25, 2020. In response to Form 19 Document number 402350573

RedRock Gathering System_Premier 6" used for LARAMIE ENERGY LLC

BLM surface

Inspected Facilities

Facility ID: 474138 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type: Sales Line	1 of Lines
----	------------------	------------

Flowline Description

Flowline Type: Sales Line Size: 6" Material: Carbon Steel
 Variance: Age: 20+ Yrs Contents: Natural Gas

Integrity Summary

Failures: Other Spills: Yes Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: No Test Result: In Process Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: At time of inspection, operator exposed flowline and found 1/2" hole in the 6 o'clock position

No form 12 or form 44 found for RedRock Gathering System_Premier 6"

Corrective Action: Provide form 12 or 44 Document numbers showing RedRock Gathering System_Premier 6" gathering line is registered with COGCC

Provide Root Cause when information becomes available. Via FIRR and email to Western Integrity inspector

Date: 04/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402353757	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106328
693200584	Area photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106321
693200585	6" gathering line	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106322