

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2020

Submitted Date:

03/25/2020

Document Number:

699800786

**FIELD INSPECTION FORM**

Loc ID 312507 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
9 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 53255  
 Name of Operator: MARALEX RESOURCES INC  
 Address: P O BOX 338  
 City: IGNACIO State: CO Zip: 81137

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Jordan, Reid	970-563-4000	maralextechjr@gmail.com	Ignacio
, Engineering		dnr_cogccengineering@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operations Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221808	WELL	SI	06/12/1983	GW	077-08410	FEDERAL 25-3	TA

**General Comment:**

[COGCC Inspection Report Summary](#)  
 On Wednesday 3/25/20 at approximately 15:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC FEDERAL-68S98W /25SESW, Location #312507 in Mesa County Colorado.  
 Refer to document #696600427 inspection conducted on 8/1/19. Not all previous corrective actions have been completed. While there, I observed normal production operations.  
 During this inspection the following possible compliance issues were observed: Access road has not been maintained. See photo #0835 with a corrective action date of 4/25/20. Multiple flow line risers not LO/TO. See photo #0837, #0838, #0839 and #0840 with a corrective action date of 3/26/20. Multiple places with debris on location. See photo #0841 with a previous corrective action date of 8/10/19. MIT required on well. With a corrective action date of 4/25/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access road has not been maintained. See photo #0835		
Corrective Action:	Repair and maintain lease road.	Date:	04/25/2020
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Multiple places with debris on location. See photo #0841		
Corrective Action:	Production facilities, shall be kept free of rubbish. Remove all debris from location.	Date:	08/10/2019
Type	UNUSED EQUIPMENT		
Comment:	Multiple flow line risers not LO/TO. See photo #0837, #0838, #0839 and #0840		
Corrective Action:	Flow line risers not LO/TO or marked are considered unused equipment. Properly lock out and tag out risers.	Date:	03/26/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 221808 Type: WELL API Number: 077-08410 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced prior to January 1999. No MIT on record.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well within two years of the initial shut-in date. Preform MIT on well.

Date: 04/25/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Ditches						
Gravel						
Berms						
		Ditches				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402352567	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105295">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105295</a>
699800787	Photos for Insp. #699800786	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105291">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105291</a>