

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2020

Submitted Date:

03/26/2020

Document Number:

700400662**FIELD INSPECTION FORM**Loc ID 397405 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 1Name of Operator: UNKNOWN

Address: _____

City: _____ State: _____ Zip: _____

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bentley, Jeff	720-283-6955	jbentley@starlight-corp.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Bentley, Brian	303-892-8830	brianbent@aol.com	
Trujillo, Aaron		aaron.trujillo@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229543	WELL	PA	01/01/1999	DA	103-07199	SILVER KING-PAN AM-HAYES 5-27	TA

General Comment:[COGCC Inspection Report Summary.](#)[On 3-25-2020 at approximately 12:15, inspector Rick Moran, conducted a follow up inspection at Twin Arrow well Silver King Pan Am Hayes 5-27 in Rio Blanco county of FIR document 200011261 dated 11-7-2000.](#)[The following compliance issues are uncompleted:](#)[1\) Unplugged open hole well.](#)[A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.](#)[This is a summary of inspection report 700400662.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 229543 Type: WELL API Number: 103-07199 Status: PA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Well drilled May 1969. Document #00600410, dated 4-16-1969 stated well was filled with shale. Original TD 2963'.

Pebble dropped in well was heard hitting a fluid at 16 seconds. No hydrocarbon smell detected.

Corrective Action: Contact dnr_cogccEngineering@state.co.us for plugging of the well.

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402353137	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105823
700400663	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105818