

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2020

Submitted Date:

03/30/2020

Document Number:

699700118

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Heil, John On-Site Inspection
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 13980
Name of Operator: RED ROCK GATHERING COMPANY LLC
Address: 999 18TH STREET STE 3400 SOUTH
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Harold Rhodes		harold.rhodes@summitmidstream.com	Environmental Remediation Manager
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
474138	SPILL OR RELEASE	AC	03/26/2020		-	RedRock Gathering System_Premier 6"	EI

General Comment:

On March 25, 2020, COGCC Environmental Staff (John Heil) and COGCC Integrity Staff (Richard Murray) conducted a field inspection of RED ROCK GATHERING COMPANY LLC (Operator #13980) Spill ID 474138 (Doc #402350573).

Summit Midstream personnel were on location during inspection.

See Richard Murray Inspection Doc #693200583.

Inspected Facilities

Facility ID: 474138 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: CONDENSATE

Estimated Spill Volume: 7.21

Comment: 3/24/2020 RED ROCK GATHERING COMPANY LLC reported a spill/release when a 6-inch gathering pipeline pressure fluctuation was observed and a surface disturbance was discovered by personnel where the pipeline ruptured. COGCC staff conducted a visual inspection of the excavation, the ground around the excavation and a small drainage located south of the excavation. RED ROCK GATHERING COMPANY LLC personnel scraped the soils around the excavation and the small drainage to address potential impacts from fluids that were released to the surface by the pipeline. COGCC staff did not observe visual or olfactory impacts at time of inspection. See photos for details.

Corrective Action: See COAs on F19 Doc #402350573.

Date: _____

Reportable: YES

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402356558	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5109851
699700119	20200325 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5109849