

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2020

Submitted Date:

04/01/2020

Document Number:

696301634

FIELD INSPECTION FORMLoc ID 433197 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433194	WELL	PR	01/02/2014	OW	123-37527	ROHN STATE LD09-65-1HN	PR
433195	WELL	PR	01/02/2014	OW	123-37528	ROHN STATE LD09-64-1HN	PR
433199	WELL	PR	12/27/2013	OW	123-37530	ROHN STATE LD09-65HN	PR
433204	WELL	PR	12/31/2013	OW	123-37533	ROHN STATE LD09-64HN	PR
433411	WELL	PR	01/22/2015	OW	123-37621	ROHN STATE LD10-65-1HN	PR
433412	WELL	PR	01/20/2015	OW	123-37622	ROHN STATE LD10-64-1HN	PR
433415	WELL	PR	01/20/2015	OW	123-37625	ROHN STATE LD10-64HN	PR
433431	WELL	PR	12/22/2014	OW	123-37637	ROHN STATE LD10-65HN	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced Water Tanks south of Crude Oil Tanks missing Signage - Content, Capacity and NFPA labels. See photos		
Corrective Action:	Comply with Rule 210.c. and 210.d.	Date:	05/01/2020
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical Containers on East and West side wells - Labels have faded no longer visible. See photos		
Corrective Action:	Comply with Rule 210.d.	Date:	05/01/2020
Type	TANK LABELS/PLACARDS		
Comment:	Compressor drainage vault - missing Signage - Content, Capacity and NFPA labels. See photos		
Corrective Action:	Comply with Rule 210.c. and 210.d.	Date:	05/01/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at Compressor drain pit. See photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."	Date:	05/01/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:				corrective date	
Type: VRT	# 3				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 8				
Comment:	Appear to be plumbed to surface				
Corrective Action:					Date:
Type: LACT	# 0				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	#				
Comment:	26				
Corrective Action:					Date:
Type: Compressor	# 2				
Comment:					
Corrective Action:					Date:
Type: VRU	# 1				
Comment:					
Corrective Action:					Date:
Type: Vertical Heater Treater	# 1				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	#				
Comment:	38				
Corrective Action:					Date:
Type: Other	#				
Comment:	26 Sand Traps				
Corrective Action:					Date:
Type: Emission Control Device	# 9				
Comment:					
Corrective Action:					Date:
Type: Vertical Separator	# 4				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 8				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL		OTHER	STEEL AST		40.765680,-103.860550	

Comment: 36							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity) 750 BBLS							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLS	STEEL AST		40.766500,-103.862190		
Comment: Maintenance Tank							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	100 BBLS	PBV FIBERGLASS		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment: Shares berm with the Crude Oil Tanks							
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	12	500 BBLs	FIBERGLASS AST		40.765740,-103.860890	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No						
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	433194	Type:	WELL	API Number:	123-37527	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433195	Type:	WELL	API Number:	123-37528	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433199	Type:	WELL	API Number:	123-37530	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433204	Type:	WELL	API Number:	123-37533	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433411	Type:	WELL	API Number:	123-37621	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433412	Type:	WELL	API Number:	123-37622	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433415	Type:	WELL	API Number:	123-37625	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433431	Type:	WELL	API Number:	123-37637	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Produced Water tanks missing Signage. Stained Soil at Compressor drain pit. Chemical Tanks at Wellheads missing labels.	petrie	04/01/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402359050	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5112492
696301635	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5112486