

NEW ELK 36-01 API# 05-071-09238 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901935



PHOTO 1: THE MAIN LEASE ROAD WAS SURFACE CROWNED TO ESTABLISH SHEET FLOW AND ELIMINATE THE TIRE RUTS.

NEW ELK 36-01 API# 05-071-09238 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901935



PHOTO 2: THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET ALONG THE MAIN LEASE ROAD.

NEW ELK 36-01 API# 05-071-09238 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 08, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901935



PHOTO 3: 04/08/20 THE UNUSED EQUIPMENT WAS REMOVED FROM LOCATION.

NEW ELK 36-01 API# 05-071-09238 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901935



PHOTO 4: REPAIRS WERE MADE TO THE PC ENGINE SKID AND THE FLUID ACCUMULATION WAS REMOVED.

NEW ELK 36-01 API# 05-071-09238 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 10, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901935



PHOTO 5: THE FLUID ACCUMULATION WAS REMOVED FROM THE LIQUID RING ENGINE SKID.