

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2020

Submitted Date:

04/20/2020

Document Number:

688800727

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 Hughes, Jim _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 1199 MAIN AVENUE SUITE 101
 City: DURANGO State: CO Zip: 81301
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475421	SPILL OR RELEASE	AC	04/14/2020		-	McCarville Waterline	EI

General Comment:

On April 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP McCarville Waterline Spill/Release Point ID #475421. For more information regarding this release, please refer to document #402370031.

Inspected Facilities

Facility ID: 475421 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spills/Releases:**Type of Spill: PRODUCED WATEREstimated Spill Volume: 23Comment: For more information regarding this release, please refer to document #402370031.Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.Date: 05/20/2020Reportable: YESGPS: Lat 37.106631Long -107.801553

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
<p>On April 16, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP McCarville Waterline Spill/Release Point ID #475421. For more information regarding this release, please refer to document #402370031.</p> <p>A Crossfire representative was on site during this inspection. The BP poly gathering line had been hydro excavated along with two Catamount pipelines, one poly and one steel. The hydro-vac crew was potholing the Catamount lines during this inspection.</p> <p>The excavated area was approximately 4' by 10', and the BP gathering line appeared to be 6-7' feet bgs.</p>	hughesjo	04/20/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402375820	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128053
688800728	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5128052