

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

696301769**FIELD INSPECTION FORM**Loc ID 454977 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neighbors, Cory		cneighbors@hpres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455070	WELL	PR	02/13/2019	OW	123-46839	RSU Anschutz Fed 4-62-02-6457C	PR
455071	WELL	PR	02/13/2019	OW	123-46840	RSU Anschutz Fed 4-62-02-4956C	PR
455072	WELL	PR	02/16/2019	OW	123-46841	RSU Anschutz Fed 4-62-11-0108C	PR
455078	WELL	PR	04/10/2019	OW	123-46846	RSU Anschutz Fed 4-62-11-1609CS	PR
455079	WELL	PR	03/10/2019	OW	123-46847	RSU Anschutz Fed 4-62-11-1609CN	PR
455081	WELL	PR	02/05/2019	OW	123-46849	RSU Anschutz Fed 4-62-02-4841CN	PR
455090	WELL	PR	02/21/2019	OW	123-46857	RSU Anschutz Fed 4-62-02-4841CS	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Tanks and West LACT, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	05/01/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 8		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 8	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 7	
Comment:		
Corrective Action:		Date:
Type: VRT	# 3	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 7	
Comment:	Appear to be plumbed to surface	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Line Heater	
Corrective Action:		Date:
Type: LACT	# 3	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	400 BBLS	STEEL AST		40.335690,-104.304270
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	455070	Type:	WELL	API Number:	123-46839	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455071	Type:	WELL	API Number:	123-46840	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455072	Type:	WELL	API Number:	123-46841	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455078	Type:	WELL	API Number:	123-46846	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455079	Type:	WELL	API Number:	123-46847	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455081	Type:	WELL	API Number:	123-46849	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455090	Type:	WELL	API Number:	123-46857	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Unmarked Risers at Tanks and West LACT	petrie	04/27/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402382060	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133663
696301770	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5133661