

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2020

Submitted Date:

04/27/2020

Document Number:

699501182**FIELD INSPECTION FORM**Loc ID 320321 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76859Name of Operator: SCHREIDER & COMPANY INCAddress: 9227 E LINCOLN AVE SUITE 200City: LONE TREE State: CO Zip: 80124**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arnold, Diana	303-659-8203	darnold@agcsi.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203445	WELL	SI	07/01/2018	OW	001-09004	COMANCHE CREEK 2-14	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

What appears to be leaking fluid from counter weight on pump jack stained soil. see pic. Unmarked barrel with no containment appears to be leaking stained soil see pic

Corrective Action:

Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.

Date: 05/04/2019

Type

OTHER

Comment:

weeds inside pump jack fence, motor house, and by wellhead see pic

Corrective Action:

Comply with Rule 603.f

Date: 05/12/2019

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment:

4' barb wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Prime Mover

1

Comment:

gas motor

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203445 Type: WELL API Number: 001-09004 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On 4/27/20 at approximately 1200, Inspector Justin Medina conducted an on-site inspection at 001-09004 Comanche Creek 2-14 Schreider & Company INC at Weld County Colorado.

This is a follow up inspection for Document # 685100894
All corrective actions are delinquent

While there, I observed shut in well.

The following possible compliance issues were observed while on location:

weeds inside pump jack fence, motor house, and by wellhead see pic 1, 2 , 5

Comply with Rule 603.f . 5/12/19

What appears to be leaking fluid from counter weight on pump jack. see pic 3, 4 , 6.

Unmarked barrel with no containment appears to be leaking see pic 7

Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. 5/4/19

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

medinaj

04/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402382248	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134120
699501183	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5134114