

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2020

Submitted Date:

05/05/2020

Document Number:

699301626

FIELD INSPECTION FORM

Loc ID 336210 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241444	WELL	PR	09/01/2017	GW	123-09233	VONASEK 8	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	PU pulley belts do not have a guard covering them		
Corrective Action:	Comply with Rule 605.c general safety	Date:	10/19/2019
Type	OTHER		
Comment:	Stained soil under gas engine skid on PU		
Corrective Action:	Comply with Rule 1002..(2).D general housekeeping	Date:	05/10/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused electric panel laying on the ground		
Corrective Action:	Comply with Rule 603.f	Date:	10/19/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Kerr McGee WH has AG fence		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Fabricated steel pipe		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 2		corrective date
Comment:	Kerr McGee Appears to be plumbed to surface, KP kauffman well does not appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas engine		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241444 Type: WELL API Number: 123-09233 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 5/5/2020 at approximately 1230 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location, Vonasek #8 at API #05-123-09233 in Weld County Colorado. While there, I observed producing wellsite. Shared location with Kerr McGee well. follow up inspection to Doc # 699300229. During this inspection the following compliance issues were observed and are now delinquent: Housekeeping: unused equipment electric panel. Comply with rule 603.f CA date 10/19/2019. See photo 3. General safety: PU pulley belt are unguarded. Comply with Rule 605.c CA date 10/19/2019 see photos 5 & 6. During this inspection the following compliance issues were observed: 1002..(2).D houskeeping: stained soil under gas engine skid. CA date 5-10-2020 see photo 4. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	05/05/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402390858	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5142867
699301627	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5142860