

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2020

Submitted Date:

05/06/2020

Document Number:

699801054

## FIELD INSPECTION FORM

 Loc ID 334074 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
 3 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 OGCC Operator Number: 34720  
 Name of Operator: GORDON ENGINEERING INC  
 Address: PO BOX 3525  
 City: GRAND JUNCTION State: CO Zip: 81502
**Contact Information:**

Contact Name	Phone	Email	Comment
Gordon, John	970-618-0811	john.gordon1gordon@yahoo.com	President
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221806	WELL	SI	02/01/2017	GW	077-08408	FEDERAL 32-1	TA

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 5/6/20 at approximately 14:30 hours, I, Inspector Corey De Paolo, conducted a follow up inspection at GORDON ENGINEERING INC FEDERAL-69S97W /32SWNW, Location #334074 in Mesa County Colorado.

Refer to document #699800382 inspection performed on 1/13/20. Not all corrective actions have been completed.

During this inspection the following possible compliance issues were observed: Weeds growing on location. See photo #1133 with a corrective action date of 5/20/20. Multiple holes in tank containment liner. See photo #1134 with a corrective action date of 6/16/20. MIT required on well. With a corrective action date of 8/6/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds growing on location. See photo #1133		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all weeds from location.		Date: 05/20/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		,
Comment:	60 bbl capacity				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Multiple holes in tank containment liner. See photo #1134			
Corrective Action:	Secondary containment structures shall be sufficiently impervious to contain discharged material. Patch all hole in tank containment liner.			Date: 06/16/2020

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 221806 Type: WELL API Number: 077-08408 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced November 2016. Meter run disconnected. No MIT on record.

Corrective Action: A mechanical integrity test shall be performed on each temporarily abandoned well within 30 days of temporarily abandoning the well. Preform MIT on well.

Date: 08/06/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Ditches				
Berms						
		Gravel				
		Compaction				
Ditches						
		Culverts				
Gravel						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402392088	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144151">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144151</a>
699801055	Photos for Insp. #699801054	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144146">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144146</a>