

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/07/2020

Submitted Date:

05/07/2020

Document Number:

700700644

FIELD INSPECTION FORM
 Loc ID 335140 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257366	WELL	PR	08/01/2018	GW	045-07547	FEDERAL RMV 123-17	PR
283969	WELL	PR	03/23/2006	GW	045-12046	FEDERAL RWF 413-17	PR
283970	WELL	PR	09/05/2006	GW	045-12045	FEDERAL RWF 313-17	PR
283971	WELL	PR	03/23/2006	GW	045-12044	FEDERAL RWF 312-17	PR
283972	WELL	PR	11/03/2006	GW	045-12048	FEDERAL RMV 168-17	PR
283973	WELL	PR	03/23/2006	GW	045-12047	FEDERAL RWF 513-17	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 5/7/20 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP RMV 123-17, at Location # 335140 in Garfield Colorado.

During this inspection the following possible compliance issues were observed:

- Two (2) rat holes are open with water in them, not sure how deep they are. Wildlife could enter and be trapped

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	911
Corrective Action:	
Date:	_____

Good Housekeeping:			
Type	OTHER		
Comment:	Two (2) rat holes are open with water in them, not sure how deep they are. Wildlife could enter and be trapped		
Corrective Action:	Eliminate the possibility of wildlife to enter	Date:	05/28/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	shared containment with condensate tanks				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	80 bbl tank in shared containment with condensate tanks and other produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspector Name: Ramsey, Scott

Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	300 BBLs	STEEL AST		,		
Comment:							
Corrective Action:							Date:
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:							Date:
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:							Date:
Flaring:							
Type							
Comment:							
Corrective Action:							Date:

Inspected Facilities						
Facility ID:	257366	Type:	WELL	API Number: 045-07547	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	283969	Type:	WELL	API Number: 045-12046	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	283970	Type:	WELL	API Number: 045-12045	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	283971	Type:	WELL	API Number: 045-12044	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	283972	Type:	WELL	API Number: 045-12048	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	283973	Type:	WELL	API Number: 045-12047	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Rip Rap				
Gravel		Gravel				
Ditches		Ditches				
Berms		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402392855	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144898
700700650	Photos for RMV 123-17	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144893