

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2020

Submitted Date:

05/08/2020

Document Number:

690005721

**FIELD INSPECTION FORM**Loc ID 332856 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246893	WELL	PA	12/03/2018	GW	123-14690	PLUSS L11-3	PA

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 246893 Type: WELL API Number: 123-14690 Status: PA Insp. Status: PA

**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Flow line (Photo 1) and riser (Riser) improperly abandoned.  
GPS data available on photos.

Corrective Action: Contact COGCC Engineering Integrity Group. Date: 06/08/2020

**COGCC Comments**

Comment	User	Date
<p>On Friday, May 8, 2020 at 11:46, I, Craig Carlile conducted an on-site inspection at:            COGCC location number: 332856            Operated by: Anadarco            While there I observed: Improperly abandoned flow line and riser.            Weather: Skies: Partly Cloudy, Wind: Calm, Temp 44 Degrees F            Please contact Engineering Integrity Group to establish a plan to address the proper            abandonment of the flow line and riser equipment show in the photos attached to this            inspection.            This is a summary of the inspection report.</p>	carlilec	05/08/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402393624	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145727">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145727</a>
690005722	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145726">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145726</a>