

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2020

Submitted Date:

05/17/2020

Document Number:

700401505

FIELD INSPECTION FORMLoc ID 336550 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10342

Name of Operator: WOODARD* SANDRA K

Address: 602 OURAY AVENUE

City: GRAND JUNCTION State: CO Zip: 81501

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
,	970-261-6589	3oilwells@gmail.com	
Burger, Craig		craig.burger@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229623	WELL	SI	06/01/2019	OW	103-07280	STAGNER RECTOR 7	SI

General Comment:

On 5-15-2020 inspector Rick Moran conducted a follow up inspection at Woodard Sandra K well Stagner 7 in Rio Blanco county of FIR documents:

- 1) 679705374 dated 9-6-2019.
- 2) 700400162 dated 2-24-2020.

The following compliance issues are uncompleted:

- 1) Stained & oily soil around pump jack. Photo 3 Complete by 10-9-2019.
- 2) Open bucket of fluid next to well head. Photo 3. Complete by 10-9-2019.

This is a summary of inspection report 700401505.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Open bucket of fluid next to well head. Bucket without wildlife protection & could be tipped over.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019
Type	OTHER		
Comment:	Stained soil around well head and flow line.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	YES		
Comment:	Casing open to atmosphere. A gas odor was detected & infrared movies were recorded during this inspection of the gas venting. During inspection 679705374 a 3 cubic ft bag filled in 12 minutes with gas. Well located 800 ft from the nearest residence.		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 229623 Type: WELL API Number: 103-07280 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last recorded production May 2019.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: _____ (mph) Direction From: _____ Weather: Partly Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
2:25	PM	2:40	PM	Wellhead(s)

Comment: FLIR camera used to image casing gas venting.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402400181	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152341
700401506	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152332
700401507	Infrared movie of gas venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152333
700401508	HSM infrared movie of gas venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152334