

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2020

Submitted Date:

05/17/2020

Document Number:

700401509

FIELD INSPECTION FORMLoc ID 333342 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10342

Name of Operator: WOODARD* SANDRA K

Address: 602 OURAY AVENUE

City: GRAND JUNCTION State: CO Zip: 81501

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
,	970-261-6589	3oilwells@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229705	WELL	SI	06/01/2019	OW	103-07362	STAGNER 6	SI

General Comment:

On 5-15-2020 inspector Rick Moran conducted a follow up inspection at Woodard Sandra K well Stagner 6 in Rio Blanco county of FIR documents:

- 1) 679705372 dated 9-6-2019.
- 2) 700400164 dated 2-24-2020.

The following compliance issues are uncompleted:

- 1) Stained & oily soil around pump jack. Photos 2, 7. Complete by 10-9-2019.

This is a summary of inspection report 700401509.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Stained & oily soil around well head at Stagner 6. Stained dirt pile at NW edge of location.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 3		
Comment:	Pump jack and 2 tanks not attached to a well on edge of location.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	YES		
Comment:	Casing open to atmosphere. A slight gas odor was detected & infrared movies were recorded during this inspection of the gas venting. Well located 800 ft from the nearest residence.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 229705 Type: WELL API Number: 103-07362 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last recorded production May 2019.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: _____ (mph) Direction From: _____ Weather: Partly Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
2:40	PM	2:45	PM	Wellhead(s)

Comment: FLIR camera used to image casing gas venting.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402400182	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152342
700401510	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152335
700401511	Infrared movie of gas	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152336
700401512	HSM infrared movie of gas	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152337