

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/28/2020

Submitted Date:

05/29/2020

Document Number:

700401708**FIELD INSPECTION FORM**Loc ID 335791 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Elsenser, Garrett	720-880-6340	cogcc.inspections@caerusoila ndgas.com	All Piceance inspections
Thompson, Bud		BLThomps@BLM.gov	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274964	WELL	PR	02/01/2020	GW	103-10544	FIGURE FOUR UNIT 8015D B15 498	PR
274965	WELL	PR	02/01/2020	GW	103-10543	FIGURE FOUR UNIT 8014D B15 498	PR
274967	WELL	PR	02/01/2020	GW	103-10541	FIGURE FOUR UNIT 8003D B15 498	PR

General Comment:

On 5-28-2020 inspector Rick Moran conducted a follow up inspection at Caerus well pad Figure Four 8003D B15 in Rio Blanco county of FIR document 700400634 dated 3-23-2020.

The following compliance issues are uncompleted:

- 1) 4 chemical container labels illegible. Photo 5. Complete by 5-21-2020.

Additional compliance issues:

- 1) Unused equipment by compressor building. Photo 6. Complete by 6-29-2020.
 2) Liner holes in tank secondary containment. Photos 8, 9. Complete by 6-29-2020.
 3) Gas leak at well head 103-10544 valve plug. Photo 7. Complete by 6-29-2020.

This is a summary of inspection report 700401708.

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	4 chemical container labels illegible.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	05/21/2020
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment by compressor building.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	06/29/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical.		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Bird Protectors	# 7			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 5			
Comment:	Chemical containers.			
Corrective Action:				Date:
Type: Other	# 5			
Comment:	4 equipment buildings and 1 compressor building.			
Corrective Action:				Date:
Type: Bradenhead	#			
Comment:	Gas leak at well head 103-10544 valve plug.			
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date: 06/29/2020
Type: Plunger Lift	# 3			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent		Inadequate	
Comment:	2 holes in liner.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 06/29/2020	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 274964 Type: WELL API Number: 103-10544 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 274965 Type: WELL API Number: 103-10543 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 274967 Type: WELL API Number: 103-10541 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402409225	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5162383
700401709	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5162376