

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2020

Submitted Date:

06/17/2020

Document Number:

693901915

FIELD INSPECTION FORMLoc ID 326188 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------|---------------------------------|
| Beebe, Sabre | | sabre.beebe@bpx.com | All Inspections |
| , | | SanJuanCOGCC@bp.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 216014 | WELL | PR | 04/02/2001 | GW | 067-07620 | BROWN 32-6-03 1 | RI |

General Comment:

On 6/16/2020 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

-Debris needs to be removed and properly disposed of by 7/17/2020.

See below, and attached photos for additional detail.

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 216014 | Type: | WELL | API Number: | 067-07620 | Status: | PR | Insp. Status: | RI |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? **Fail**Comment **Dense Russian thistle debris observed piled up along the eastern fenceline, approx. 4 feet high.**Corrective Action **Remove and properly dispose of debris.**Date **07/17/2020**Unused or unneeded equipment onsite? **Pass**

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

| | |
|---|---|
| 1003b. Area no longer in use? In _____ 1003c. Compacted areas have been cross ripped? _____ 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____ Cuttings management: _____ 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ Production areas have been stabilized? _____ Segregated soils have been replaced? _____ | Production areas stabilized ? In _____ |
|---|---|

RESTORATION AND REVEGETATION

Cropland

| | | |
|-------------------------|-------------------|---------------------------------------|
| Top soil replaced _____ | Recontoured _____ | Perennial forage re-established _____ |
|-------------------------|-------------------|---------------------------------------|

Non-Cropland

| | | |
|-------------------------|-------------------|--------------------------------|
| Top soil replaced _____ | Recontoured _____ | 80% Revegetation Pass _____ |
|-------------------------|-------------------|--------------------------------|

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment: Approximately 200 musk thistles observed. Most appear to be recently herbicide treated. Continued weed management will be needed. Revegetation is progressing within the interim reclamation areas.

Corrective Action: Date _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

| | |
|---------------------------------------|---|
| Date Final Reclamation Started: _____ | Date Final Reclamation Completed: _____ |
|---------------------------------------|---|

Final Land Use: _____

Reminder: _____

Comment:

| | | |
|---|---|------------------------|
| Well plugged _____ | Pit mouse/rat holes, cellars backfilled _____ | |
| Debris removed _____ | No disturbance /Location never built _____ | |
| Access Roads Regraded _____ | Contoured _____ | Culverts removed _____ |
| Gravel removed _____ | | |
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ | |
| Compaction alleviation _____ | Dust and erosion control _____ | |
| Non cropland: Revegetated 80% _____ | Cropland: perennial forage _____ | |
| Weeds present _____ | Subsidence _____ | |

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

| | | |
|---------------------------|--|--|
| Overall Final Reclamation | Well Release on Active Location <input type="checkbox"/> | Multi-Well Location <input type="checkbox"/> |
|---------------------------|--|--|

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Stormwater erosion appears to be controlled at this time.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 693901916 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5178724 |