

Interim Reclamation Inspection

June 8, 2020

Operator: ROCKY MOUNTAIN MIDSTREAM LLC #10716

Facility ID: 476934

Inspection Document #: 697501649

Weld County, CO

NWSW Section 14 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. COGCC COGIS 2017 aerial imagery illustrates approximate areas concerning a complaint filed by the surface owner. An active crude oil line (orange line) was first installed and then a second line (gas) was installed later. The second line is associated with the complaint issues.

Inspection Photos
Location Name: To Be Determined
Facility ID: 476934



Photo 2. Photo taken from a portion of the line, facing North. Photo illustrates vegetation along the line is not reflective of reference areas. It appears the line has not been properly contoured to allow successful flood irrigation. Complainant indicated that irrigation water ponds along the line which should continue to flow east. Vegetative growth has been negatively affected along the line which is a likely result of ponding water.



Inspection Photos
Location Name: To Be Determined
Facility ID: 476934



Photo 3. Photo taken from a portion of the line, facing South. See comments under Photo 2.



Inspection Photos
Location Name: To Be Determined
Facility ID: 476934



Photo 4. Photo taken from a section just east of the line, facing East. Photo illustrates an area where “topsoil” was imported. Based on field observations, there is no desirable vegetative growth throughout this section which indicates this imported “topsoil” is not suitable for vegetative growth.

Inspection Photos
Location Name: To Be Determined
Facility ID: 476934



Photo 5. Photo taken from the same section from Photo 4, facing South. See comments under Photo 4.



Inspection Photos
Location Name: To Be Determined
Facility ID: 476934



Photo 6. Photo taken from a section east of the line, facing West. Photo illustrates an area where an Operator was observed, by the complainant, who was off the easement and caused damage a portion of the irrigation system and damaged the field.



Inspection Photos
Location Name: To Be Determined
Facility ID: 476934



Photo 7. Reference photo taken east of the line, facing East. Photo illustrates the line areas and other sections shown in Photos 4-6 are not reflective of reference areas.

