

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2020

Submitted Date:

06/18/2020

Document Number:

696201425**FIELD INSPECTION FORM**

Loc ID 335716 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		jcobbb@bry.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290824	WELL	PR	05/07/2014	GW	045-14204	BERRY 1-21D	RI
292174	WELL	PR	10/02/2008	GW	045-14629	BERRY 1-20D	RI
292175	WELL	PR	04/14/2009	GW	045-14628	BERRY 1-19D	RI
292176	WELL	PR	04/14/2009	GW	045-14627	BERRY 1-18D	RI
292177	WELL	DA	03/23/2008	DA	045-14626	BERRY 1-17D	RI
292178	WELL	PR	01/01/2020	GW	045-14625	BERRY 1-22D	RI
292179	WELL	AL	10/24/2017	LO	045-14624	BERRY 1-31D	RI
292180	WELL	AL	10/24/2017	LO	045-14623	BERRY 1-32D	RI
292181	WELL	AL	10/24/2017	LO	045-14622	BERRY 1-33D	RI
292182	WELL	AL	10/24/2017	LO	045-14621	BERRY 1-34D	RI
292183	WELL	AL	10/24/2017	LO	045-14620	BERRY 1-35D	RI
292185	WELL	PR	04/14/2009	GW	045-14619	BERRY 1-36D	RI
335716	LOCATION	AC			-	BERRY F01 697	RI

**General Comment:**

On 6/17/2020, Reclamation Specialist Trujillo conducted a reclamation and stormwater inspection on Berry Petroleum's Berry F1 697 location in Garfield County, Colorado.

It was observed in this inspection that an active remediation project for land farming activities exists on the Location.

The following compliance issues were observed during this inspection:

1003.a: Marking guy line anchors

1004.a: Reclamation of abandoned wells.

Refer to the "Reclamation" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	<u>290824</u>	Type:	<u>WELL</u>	API Number:	<u>045-14204</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292174</u>	Type:	<u>WELL</u>	API Number:	<u>045-14629</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292175</u>	Type:	<u>WELL</u>	API Number:	<u>045-14628</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292176</u>	Type:	<u>WELL</u>	API Number:	<u>045-14627</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292177</u>	Type:	<u>WELL</u>	API Number:	<u>045-14626</u>	Status:	<u>DA</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292178</u>	Type:	<u>WELL</u>	API Number:	<u>045-14625</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292179</u>	Type:	<u>WELL</u>	API Number:	<u>045-14624</u>	Status:	<u>AL</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292180</u>	Type:	<u>WELL</u>	API Number:	<u>045-14623</u>	Status:	<u>AL</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292181</u>	Type:	<u>WELL</u>	API Number:	<u>045-14622</u>	Status:	<u>AL</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292182</u>	Type:	<u>WELL</u>	API Number:	<u>045-14621</u>	Status:	<u>AL</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292183</u>	Type:	<u>WELL</u>	API Number:	<u>045-14620</u>	Status:	<u>AL</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292185</u>	Type:	<u>WELL</u>	API Number:	<u>045-14619</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>335716</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>RI</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Fail

Comment

It was observed in this inspection that anchors have not been marked in accordance with Rule 1003.a

Corrective Action

Install proper guy line markers per Rule 1003.a

Date **07/03/2020**

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

## 1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment Active remediation project occurring on areas not needed for production. See Project #10044 for additional details. Interim reclamation due upon closure of the remediation project.

Corrective Action  Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: It was observed in this inspection that all permitted wells on this location have either been drilled and are producing, or have been abandoned.

It was observed that cellars, and possible conductor settings, associated with the abandoned wells have not been removed.

Inspector Name: Trujillo, Aaron

Corrective Action:	<b>Comply with 1004 rules and remove remaining unused or unneeded cellars/conductor settings remaining on the Location.</b>	Date <b>07/18/2020</b>				
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>				
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <b>BMPs observed appear to be in proper functioning condition. No erosion issues observed.</b>						
Corrective Action: <input type="text"/>						Date: <input type="text"/>
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402426386	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5179413">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5179413</a>
696201426	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5179392">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5179392</a>