

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2020

Submitted Date:

06/18/2020

Document Number:

699301955

FIELD INSPECTION FORM

Loc ID 331207 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259370	WELL	SI	12/01/2018	GW	123-20312	COYLE 13-18A	SI

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	Weeds growing accross access road			
Corrective Action	Comply with Rule 603.f			Date: 07/02/2020
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	weeds starting to grow inside Ag fence			
Corrective Action:	Comply with Rule 603.f			Date: 07/02/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Ag fence			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	automation			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	appears to be plumbed to surface			
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 259370 Type: WELL API Number: 123-20312 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since 12-1-2018 Form 42 (PR) Doc # 402356464 submitted on 3-30-2020 and is approved

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 6/18/2020 at approximately 1055 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: right;">Coyle 13-18A at API #05-123-20312</p> <p>in Weld County Colorado.</p> <p>While there, I observed shut in well site. SI since 12-1-2018, Form 42 (PR) Doc # 402356464 submitted on 3-30-2020 and is approved.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>603.f housekeeping: weeds growing across and along access road. CA date 7-2-2020 see photos 3 & 4.</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	06/18/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402426466	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5179497
699301956	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5179491