

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2020

Submitted Date:

06/18/2020

Document Number:

700402013

FIELD INSPECTION FORMLoc ID 314959 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10725

Name of Operator: VALKYRIE OPERATING LLC

Address: 1600 STOUT STREET SUITE 1000

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|--------------|-------------------------------|-----------------|
| Thompson, Bud | | BLThomps@BLM.gov | |
| Dunham, Tyson | 307-388-2290 | tdunham@valkyrieoperating.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 229977 | WELL | PA | 08/06/2015 | OW | 103-07636 | UNITED STATES B 2 | PA |

General Comment:

On 6-17-2020 inspector Rick Moran conducted a follow up inspection at Valkyrie Operating well United States B 2 in Rio Blanco county of FIR document 675101224 dated 4-3-2015.

The following compliance issues were resolved:

- 1) The incomplete signage no longer needed due to the P&A status.
- 2) The MIT is not longer needed due to the P&A status.

Additional compliance issues:

- 1) Removal of pump jack. Photos 1 & 2. Complete by 9-18-2020.

This is a summary of inspection report 700407636.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

| | | | |
|--------------------|------------------------------------|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Pump jack present on P&A location. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 09/18/2020 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 229977 Type: WELL API Number: 103-07636 Status: PA Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well P&A in August 2015.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 402425546 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5178503 |
| 700402014 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5178482 |