

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2020

Submitted Date:

06/17/2020

Document Number:

700900154**FIELD INSPECTION FORM**Loc ID 320324 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76859Name of Operator: SCHREIDER & COMPANY INCAddress: 9227 E LINCOLN AVE SUITE 200City: LONE TREE State: CO Zip: 80124**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|---------------------------------|--------------------------|---------|
| Schneider, Jeff | 970-867-9437/ (214) 244-3819 | jeff@schneiderenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 203451 | WELL | SI | 07/01/2018 | OW | 001-09010 | COMANCHE CREEK 1-14 | SI |

General Comment:

| Location | | | | |
|--|--|--------|--|------------------|
| Lease Road: | | | | |
| Type | Main | | | |
| comment: | Adequate | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | BATTERY | | | |
| Comment: | Adequate | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Adequate | | | |
| Corrective Action: | | | | Date: |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | Adequate | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | Adequate | | | |
| Corrective Action: | | | | Date: _____ |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | TANK BATTERY | | | |
| Comment: | Inadequate fencing or fencing in disrepair. | | | |
| Corrective Action: | Location is within a designated setback location, install or repair fencing per Rule 604.c. (2)M. 15 days. Corrective action Date See attached photo #.1 | | | Date: 07/06/2020 |
| Equipment: | | | | |
| Type: Bradenhead | # 1 | | | corrective date |
| Comment: | Appears to be plumbed to surface. | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 3 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | |
|-----------------------------------|-----|-------|
| Type: Bird Protectors | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 4 | OTHER | STEEL AST | | 39.880302,-104.294079 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|--------------------------------------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 2 tanks 210bbls and 2 tanks 300 bbls | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|---|---------------------|---------------------|------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Insufficient | Base Insufficient | Inadequate |
| Comment: | Inadequate berms around tank(s). | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective action Date 7/6/2020 See attached photos #.1 &2. | | | Date: 07/06/2020 |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 203451 Type: WELL API Number: 001-09010 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadComment: Appears to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| <p>COGCC Inspection Report Summary.</p> <p>On Friday June 12, 2020 at approximately 10:55am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Comanche Creek 1-14, Schreider and Company INC at API # 001-0910 in Adams County Colorado.</p> <p>While there, I observed a Shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Inadequate berms around tank(s). Repair or install berms or other secondary containment devices per Rule 605.a.(4). Corrective action Date 7/6/2020 See attached photos #.1 &2.</p> <p>Inadequate fencing or fencing in disrepair. Location is within a designated setback location, install or repair fencing per Rule 604.c.(2)M. Corrective action Date 7/6/2020 See attached photo #.1</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | finkenbc | 06/17/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402425769 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5178794 |
| 700900155 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5178792 |