

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2020

Submitted Date:

07/08/2020

Document Number:

688308147

FIELD INSPECTION FORMLoc ID 432243 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 19160

Name of Operator: CONOCO PHILLIPS COMPANY

Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX Zip: 77079

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|-----------------------------------|------------------------|
| Crestone Peak | 303-268-3703 | cogcc.inspections@crestonepr.com | Watkins Office Phone # |
| Knutson, Danny | 970-309-7510 | danny.knutson@crestonepr.com | |
| ConocoPhillips | | COPColoradoReg@conocophillips.com | All Inspections |
| Burn, Diana | | diana.burn@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 432242 | WELL | DG | 06/10/2013 | OW | 005-07205 | Tebo 33 1H | SI |

General Comment:

Routine Inspection

Form 10 is in process: 402310229 10 (CO) (CC) IN PROCESS 03/16/2020 CONOCO PHILLIPS COMPANY

DG status.

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | lease sign at gate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 303-659-7740

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | OTHER | | |
| Comment: | Mechanical conditions-leak at union near wellhead on ground (see attached photo). | | |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | Date: | 07/29/2020 |

Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------|-------|--|
| Type | PUMP JACK | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | | | |
|---------------------------------|----------------------|--|-------|-----------------|--|
| Equipment: | | | | corrective date | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | -1.49 psi | | | | |
| Corrective Action: | | | Date: | | |
| Type: Bird Protectors | # 5 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |
| Type: VRU | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |
| Type: Emission Control Device | # 2 | | | | |
| Comment: | on auto (blue light) | | | | |
| Corrective Action: | | | Date: | | |
| Type: Horizontal Heater Treater | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |
| Type: Flow Line | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |
| Type: Prime Mover | # 1 | | | | |
| Comment: | electric | | | | |
| Corrective Action: | | | Date: | | |
| Type: VRT | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |
| Type: Pump Jack | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |
| Type: Gas Meter Run | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |
| Type: Flare | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | Date: | | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 400 BBLs | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|-------------------------------------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | same metal berms as crude oil tanks | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 3 | 400 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Location Construction

Location ID: 432242 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 432242 Type: WELL API Number: 005-07205 Status: DG Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since 11/1/2019.

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 402439871 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5192534 |
| 688308155 | Conoco Phillips Tebo 33 1H | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5192520 |