

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/07/2020

Submitted Date:

07/07/2020

Document Number:

699801384

FIELD INSPECTION FORM

Loc ID 314169 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100321
 Name of Operator: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS
 Address: 1515 ARAPAHOE ST TOWER 1
 City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
hills, black		jessicadonahue@summiteng.net	
service, forest		kkmobley@fs.fed.us	

General Comment:

[COGCC Inspection Report Summary](#)
 On Tuesday 7/7/20 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY WOLF CREEK UNIT68S90W /35SENW, Location #314169 in Pitkin County Colorado.
 Refer to document #692402270 inspection conducted on 5/28/20. All previous corrective actions have been completed.
 While there, I observed normal production operations.
 During this inspection the following possible compliance issues were observed: Multiple tanks missing required information. See photo #1463, #1464, #1465 and #1466 with a corrective action date of 10/7/20.

 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Lease Road:

Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Multiple tanks missing required information. See photo #1463, #1464, #1465 and #1466		
Corrective Action:	All tanks with a capacity of ten (10) barrels or greater shall be labeled with name of operator, operator's emergency contact telephone number, tank capacity, tank contents and (NFPA) Label.	Date:	10/07/2020
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:

				corrective date
Type: Deadman # & Marked	# 1			
Comment:				
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Gas storage building			
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	OTHER	STEEL AST		
Comment: 120 bbl capacity					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		
Comment: Tank contents and capacity not labeled					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		
Comment: Clear diesel tank capacity not labeled					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
GLYCOL	1	OTHER	STEEL AST		,
Comment: Capacity not labeled					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	3	OTHER	STEEL AST		,
Comment: Capacity not labeled					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Culverts	Pass			
Berms	Pass					
		Sediment Traps	Pass			
		Ditches	Pass			
		Berms	Pass			
Sediment Traps	Pass					
Ditches	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402439234	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5191998
699801393	Photos for Insp. #699801384	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5191994