

Inspection Photos
Operator: BP America
API: 067-08507
Date: 8/3/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with smooth brome, crested wheatgrass, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of the southern project area from the southeastern corner facing northward.



Photo 4. View of erosional channel approximately 2 feet wide and 1.5 feet deep, starting along the southwestern edge and flowing through the southern interim reclamation area.



Photo 5. Another view of erosional channel in the southern project area. Cobble BMPs are not sufficient here and no longer functioning.

Spotted knapweed
appears to be herbicide
treated



08-03-2023

Spotted knapweed
rosette is not herbicide
treated



08-03-2023

Photos 6/7. View of spotted knapweeds, large individuals are herbicide treated (left), smaller rosettes remain untreated (right).



Photo 8. View of reference area vegetation comprised of sagebrush shrubland with understory of blue grama, sand dropseed, and hedgehog cactus.