

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2020

Submitted Date:

08/12/2020

Document Number:

700402846**FIELD INSPECTION FORM**Loc ID 315200 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	<a href="#">All inspections</a>
Thompson, Bud		BLThomps@BLM.gov	
Heil, John		john.heil@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230404	WELL	PA	05/19/2014	GW	103-08066	PHILADELPHIA CREEK 18	PA

**General Comment:**

A routine inspection identified the following compliance issues:

- 1) Unused equipment & trash on location. Photos 4, 5, 6, 7, 8. Complete by 9-11-2020.
- 2) Submit Form 27 for pit closure. Photo 3. Complete by 9-11-2020.

Note: Same inspection as 700402839 with the photo attachment included.

This is a summary of inspection report 700402846.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Used equipment and trash on locaton: 2 deadman, 1 wood timber, 2 steel cables, 4 metal fence posts.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/11/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	Flow line riser on edge of location.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 230404 Type: WELL API Number: 103-08066 Status: PA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: P&A in May 2014.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat: 40.032340Long: -108.988220

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective

Date:

**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

[Submit Form 27 for pit closure.](#)

Corrective

[Submit reports as per Rule 206.](#)Date: 09/11/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700402847	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221952</a>