

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/12/2020

Submitted Date:

08/12/2020

Document Number:

695103160**FIELD INSPECTION FORM**

Loc ID 308722 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279628	WELL	PR	05/01/2020	GW	071-08511	BLUESKY 44-17	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: UNUSED EQUIPMENT (GAS ENGINE SKID IS NOT CONNECTED).		
Corrective Action:	REMOVE UNUSED EQUIPEMNT OR PUT EQUIPMENT INTO USE, COMPLY WITH RULE 603.f. NOTE: THIS IS THE SECOND NOTICE OF THIS CA FOR THIS LOCATION.	Date:	11/12/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	PHOTO 3: NO CURRENT CALIBRATION ON GAS METER.		
Corrective Action:	Provide calibration records or calibrate meter as required by Rule 329.	Date:	09/12/2020

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 279628	Type: WELL	API Number: 071-08511	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 280378Lat: 37.166153Long: -104.796097Reference Point: SEOther: Length: 60Width: 30**Lining:**Liner Type: Liner Condition: Comment:

Corrective

Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment:

Corrective

Date: **Netting:**Netting Type: Netting Condition: Comment:

Corrective

Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: NOComment: PHOTO 5: NO FREEBOARD MARKER IN PRODUCED WATER PIT.

Corrective

INSTALL FREEBOARD MARKER, COMPLY WITH RULE 902.b.Date: 11/12/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402470368	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227256
695103161	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227247