

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2020

Submitted Date:

08/27/2020

Document Number:

700403118

FIELD INSPECTION FORM

Loc ID 314354 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10605
Name of Operator: APEX OIL VENTURES INC
Address: 8823 S. REDWOOD ROAD #D-1
City: WEST JORDAN State: UT Zip: 84088

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Callister, Jan	801-487-4721	jec-apex@outlook.com	
Hayes, Mike	970-620-2257	hayespetroleum@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228525	WELL	PR	04/01/2020	GW	103-05400	P.R.-TRIGOOD-GOV'T (0365) 10	PR

General Comment:

A routine inspection identified the following compliance issues:
1) Remove old operator sign located at pump jack. Photo 5. Complete by 9-27-2020.

This is a summary of inspection report 700403118.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Remove old operator well sign located at pump jack.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/27/2020

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Deadman # & Marked	# 2		
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>
Type: Pump Jack	# 1		
Comment:	Pump jack power disconnected.		
Corrective Action:		Date:	<input type="text"/>

Venting:

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Inspected Facilities

Facility ID: 228525 Type: WELL API Number: 103-05400 Status: PR Insp. Status: PR

Producing Well

Comment: Tubing valve close. Casing valve open at well head. Casing gage 90 psi.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402476161	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5233329
700403119	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5233327