

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds.		
Corrective Action:	Weeds. Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 9/11/2020. See attached photos # 1 through 4.	Date:	09/11/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	4 staned barbed wire		
Corrective Action:		Date:	
Equipment:			
Type: Emission Control Device # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Bird Protectors # 1			
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator # 1			
Comment:			
Corrective Action:			Date:
Type: Pump Jack # 1			
Comment:			
Corrective Action:			Date:

Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.891106,-104.181665
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 201831 Type: WELL API Number: 001-07235 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday August 12, 2020 at approximately 9:45am, I, Inspector Chane Finkenbinder, conducted an on-site inspection at Champlin 459 Amoco #1, Painted Pegasus Petroleum at API #001-07235 in Adams County Colorado. While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Weeds. Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 9/11/2020. See attached photos # 1 through 4. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	08/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402476596	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5233680
700900324	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5233676