

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2020

Submitted Date:

09/02/2020

Document Number:

699801725

FIELD INSPECTION FORM

Loc ID 312424 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@maralexinc.com	
, Engineering		dnr_cogccengineering@state.co.us	
, BLM		jbyers@blm.gov	
Jordan, Reid		maralextechjr@gmail.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221569	WELL	SI	01/01/1999	GW	077-08171	FEDERAL 29-2	TA

General Comment:

COGCC Inspection Report Summary

On Wednesday 9/2/20 at approximately 11:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC FEDERAL-68S97W /29SWNW, Location #312424 in Mesa County Colorado. Refer to document #699801090 inspection conducted on 5/13/20. Not all corrective actions have been completed.

During this inspection the following possible compliance issues were observed: Flow line riser not LO/TO. See photo #1170 and #1828 with a previous corrective action date of 8/13/20. Unused meter run. See photo #1166 and #1827 with a previous corrective action date of 8/13/20. Multiple unmarked deadman. See photo #1168, #1169 and #1830 with a previous corrective action date of 5/27/20. MIT required on well. With a previous corrective action date of 8/13/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Flow line riser not LO/TO. See photo #1170 and #1828		
Corrective Action:	Flow line risers not LO/TO or marked are considered unused equipment. Properly LO/TO or plug flow line riser.		Date: <u>08/13/2020</u>
Type	STORAGE OF SUPL		
Comment:	Unused meter run. See photo #1166 and #1827		
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused equipment from location.		Date: <u>08/13/2020</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 2		
Comment:	Multiple unmarked deadman. See photo #1168, #1169 and #1830		

Corrective Action:	All guy line anchors left buried for future use shall be identified by a marker of bright color not less than four (4) feet in height. Properly mark deadman.	Date:	05/27/2020
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 221569 Type: WELL API Number: 077-08171 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced prior to 1999. No MIT on record.

Corrective Action: All temporarily abandoned wells shall pass a mechanical integrity test. Preform MIT on well.

Date: 08/13/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402481973	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5238919
699801726	Photos for Insp. #699801725	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5238912