

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2020

Submitted Date:

09/14/2020

Document Number:

690200648

FIELD INSPECTION FORM

Loc ID 309402 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergyllc.com	
Fitzgerald, Edie		ediefitzgerald@tcenergyllc.com	
BAKER DAVID		dbaker@auroramp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
164	WELL	PR	01/21/2009	GW	071-09485	GOLDEN EAGLE 28-01	RI

General Comment:

This is a stormwater management inspection.
See attached photos and additional details within this report.

Operator is directed to perform corrective actions outlined on this inspection report immediately. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an area along the road where stormwater is not properly diverted to the culvert.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment: _____

Corrective

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Inadequate

Comment: The electric fencing around the pit is in disrepair.

Corrective

Repair fence

Date: _____

Netting:

Netting Type: Netting Condition:

Comment: _____

Corrective

Date: _____

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	300259	1841334	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402488625	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246612
690200649	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246607