



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	unused electricpanel leaning on fence		
Corrective Action:	Comply with Rule 603.f	Date:	12/14/2020
Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Comply with Rule 907.e	Date:	12/14/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	chainlink		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	transformers, meter box & electric panel		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241406 Type: WELL API Number: 123-09195 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Scout card shows well as PR at the time of inspection well appear to be SI all valves are closed and the electric power is off.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Monday 9/14/2020 at approximately 1520 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Painted Pegasus Petroleum LLC location:</p> <p style="text-align: right;">Oskarson #3 at</p> <p>API #05-123-09195 in Weld County Colorado.                      While there, I observed a wellsite. Scout card shows well as PR at the time of inspection well appear to be SI all valves are closed and the electric power is off.                      During this inspection the following possible compliance issues were observed:                      603.f housekeeping: unused electric panel leaning on fence, CA date 12 14 2020. see photo 4.                      907.e housekeeping: stained soil around WH, CA date 12-14-2020 see photos 2, 6 &amp; 7. See attached photos.                      Location is dry, weather is clear.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	09/14/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402488908	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246891">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246891</a>
699302554	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246886">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246886</a>