

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2020

Submitted Date:

09/23/2020

Document Number:

696302516

FIELD INSPECTION FORM

Loc ID 454815 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

25 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|----------------------|---------|
| Neighbors, Cory | | cneighbors@hpres.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------------|-------------|
| 454809 | WELL | PR | 03/01/2020 | | 123-46726 | RSU Anschutz Fed 4-61-04-4040C | PR |
| 454811 | WELL | PR | 03/01/2020 | | 123-46727 | RSU Anschutz Fed 4-61-04-0909CS | PR |
| 454814 | WELL | PR | 03/01/2020 | | 123-46728 | RSU Anschutz Fed 4-61-04-0808C | PR |
| 454816 | WELL | DG | 06/17/2019 | | 123-46729 | RSU Anschutz Fed 4-61-04-2525C | DG |
| 454817 | WELL | PR | 02/01/2020 | | 123-46730 | RSU Anschutz Fed 4-61-04-0909CN | PR |
| 454819 | WELL | PR | 03/01/2020 | | 123-46731 | RSU Anschutz Fed 4-61-04-2424C | PR |
| 463781 | WELL | PR | 02/01/2020 | | 123-50078 | RSU Anschutz Fed 4-61-5-0909CN | PR |
| 463782 | WELL | PR | 04/01/2020 | OW | 123-50079 | RSU Anschutz Fed 4-61-5-2421C | PR |
| 463783 | WELL | PR | 03/01/2020 | | 123-50080 | RSU Anschutz Fed 4-61-5-2528C | PR |
| 463784 | WELL | PR | 03/01/2020 | | 123-50081 | RSU Anschutz Fed 4-61-5-4040C | PR |
| 463785 | WELL | PR | 03/01/2020 | | 123-50082 | RSU Anschutz Fed 4-61-05-0909CS | PR |
| 463786 | WELL | PR | 02/01/2020 | OW | 123-50083 | RSU Anschutz Fed 4-61-5-0808C | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unmarked Risers at VRUs. See photos | | |
| Corrective Action: | Comply with Rule 603.f. | Date: | 09/25/2020 |
| Type | TRASH | | |
| Comment: | Locate Flags on the majority of location. See photos | | |
| Corrective Action: | Comply with Rule 603.f. | Date: | 10/09/2020 |
| Type | OTHER | | |
| Comment: | Stained Soil at Wellheads. See photos | | |
| Corrective Action: | For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e." | Date: | 10/09/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------|-------|--|
| Type | LOCATION | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|-----|-------|-----------------|
| Type: VRU | # 6 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|--|--|-------|
| Type: Horizontal Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 11 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pig Station | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # | | |
| Comment: | 26 | | |
| Corrective Action: | | | Date: |
| Type: LACT | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | 4-61-04-2525C - TA Wellhead. Well not completed yet. | | |
| Corrective Action: | | | Date: |
| Type: VRT | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Other | # 1 | | |
| Comment: | Line Heater | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 12 | | |
| Comment: | Appear to be plumbed to surface | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 14 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 2 | 400 BBLs | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|-----------|----------|--|
| Condition | Adequate | |
|-----------|----------|--|

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|-----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 10 | 400 BBLS | STEEL AST | | 40.346750,-104.224200 |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------------------------|-------|---|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 454809 | Type: | WELL | API Number: | 123-46726 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 454811 | Type: | WELL | API Number: | 123-46727 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 454814 | Type: | WELL | API Number: | 123-46728 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 454816 | Type: | WELL | API Number: | 123-46729 | Status: | DG | Insp. Status: | DG |
| Idle Well | | | | | | | | | |
| Purpose: | <input type="checkbox"/> Shut In | | <input checked="" type="checkbox"/> Temporarily Abandoned | | Reminder: | | | | |
| Comment: | TA Not Completed | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 454817 | Type: | WELL | API Number: | 123-46730 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 454819 | Type: | WELL | API Number: | 123-46731 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 463781 | Type: | WELL | API Number: | 123-50078 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 463782 | Type: | WELL | API Number: | 123-50079 | Status: | PR | Insp. Status: | PR |

| <u>Producing Well</u> | | | |
|---|----|-------|--|
| Comment: | PR | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>463783</u> Type: <u>WELL</u> API Number: <u>123-50080</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| <u>Producing Well</u> | | | |
| Comment: | PR | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>463784</u> Type: <u>WELL</u> API Number: <u>123-50081</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| <u>Producing Well</u> | | | |
| Comment: | PR | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>463785</u> Type: <u>WELL</u> API Number: <u>123-50082</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| <u>Producing Well</u> | | | |
| Comment: | PR | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>463786</u> Type: <u>WELL</u> API Number: <u>123-50083</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| <u>Producing Well</u> | | | |
| Comment: | PR | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| Routine Field Inspection. Stained Soil at Wellheads. Unmarked Risers at VRUs. Locate Flags on Location no longer in use | petrie | 09/23/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402496433 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5254366 |
| 696302517 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5254363 |