

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2020

Submitted Date:

10/01/2020

Document Number:

699801872

**FIELD INSPECTION FORM**

Loc ID 427218 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Gunnison		GEOps@oxbow.com	
, Gunnison		jessicadonahue@summiteng.net	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427223	WELL	PR	08/12/2013	GW	051-06103	DGU Hotchkiss Federal 1289 18-H1	PR
427241	WELL	PR	11/15/2012	GW	051-06104	DGU Hotchkiss Federal 1289 18-H2	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Thursday 10/1/20 at approximately 12:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at GUNNISON ENERGY LLC DGU Federal 1289 /Section 18 Pad, Location #324485 in Gunnison County Colorado.  
 While there, I observed normal production operations.  
 During this inspection the following possible compliance issues were observed: Multiple places with unused equipment on location. See photo #1970, #1971 and #1972 with a corrective action date of 10/22/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	970-874-7697		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Multiple places with unused equipment on location. See photo #1970, #1971 and #1972		
Corrective Action:	production facilities, shall be kept free of the following: equipment, vehicles, and supplies not necessary for use on that lease		Date: 10/22/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 9		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on free flow no tools on well.		
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Generator		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Line heater		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks by wellheads		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 427223 Type: WELL API Number: 051-06103 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 427241 Type: WELL API Number: 051-06104 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
Gravel						
		Sediment Traps				
		Berms				
Sediment Traps						
		Gravel				
Ditches						
Berms						
		Ditches				
		Culverts				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402502682	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261516">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261516</a>
699801873	Photos for Insp. #699801872	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261512">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5261512</a>