

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2020

Submitted Date:

10/06/2020

Document Number:

699302733**FIELD INSPECTION FORM**Loc ID 331666 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264575	WELL	SI	04/01/2017	GW	123-21091	OZBUN 10-19	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds growing around wellsite and ECD @ TB		
Corrective Action:	Comply with Rule 603.f	Date:	10/20/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbwire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Ag fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	

Equipment:				corrective date	
Type: Ancillary equipment	# 3				
Comment:	automation				
Corrective Action:			Date:		
Type: Gas Meter Run	# 2				
Comment:	locks on doors and ar inaccessible (Brown Meter houses)				
Corrective Action:			Date:		
Type: Bradenhead	# 1				
Comment:	exposed at surface				
Corrective Action:			Date:		
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:			Date:		
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:			Date:		
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:			Date:		
Type: Gas Meter Run	# 1				
Comment:	card in meter house indicates current calibration.				
Corrective Action:			Date:		
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:			Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	315 bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:		Shares containment with crude tank				
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 264575 Type: WELL API Number: 123-21091 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since 4-1-2017.

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Tuesday 10/6/2020 at approximately 1230 hrs. I, Inspector Robbie Revas,
 Conducted an on-site inspection at a Noble Energy location:
 Ozbun 10-19 at API #05-123-21091 in Weld County Colorado.
 While there, I observed a SI Wellsite & Tank battery.
 During this inspection the following possible compliance issue was observed:
 603.f housekeeping: dead weeds around Wellsite and ECD, CA date 10-20-2020.
 See attached photos.
 Location is dry, weather is clear.
 A follow up on this site inspection needs to be conducted to ensure the
 Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

revasr

10/06/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402504698	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5263636
699302734	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5263634