

Inspection Photos

Operator: Hilcorp Energy
API: 067-08409
Date: 10/15/2020



Photo 1. View of the project area from the northwestern corner facing center. Mowed pasture grasses such as smooth brome present.



Photo 2. View of erosional channels and failed wattles within the southeastern project area. Erosional channels up to approximately 4 feet deep present here.



Photo 3. View of sediment deposition within the southeastern project area.



Photo 4. View of sediment deposition, up to 2.5 feet deep within the southern project area.



Photo 5. View of the northeastern project area where wattles are full of sediment and rilling is occurring.



Photos 6/7. View of the reference area situated at the edge of the sagebrush, pinyon and juniper woodland with blue grama and sand dropseed, as well as irrigated grass field with grasses such as smooth brome.



View of closed gates used to access location.