

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/20/2020

Submitted Date:

10/20/2020

Document Number:

701100616

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
335516 \_\_\_\_\_ LONGWORTH, MIKE \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10091  
Name of Operator: BERRY PETROLEUM COMPANY LLC  
Address: 5201 TRUXTUN AVENUE #100  
City: BAKERSFIELD State: CA Zip: 90339

**Findings:**

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Armstrong, Jon		jarmstrong@bry.com	
Wilbourn, Don		dwilbourn@bry.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293395	WELL	PR	08/20/2015	OW	045-14955	SCHOOL HOUSE POINT OM1A A21 696	PR
293398	WELL	PR	05/30/2015	OW	045-14958	SCHOOL HOUSE POINT OM01D A21 696	PR
293399	WELL	PR	06/03/2015	OW	045-14959	SCHOOL HOUSE POINT OM02A A21 696	PR
293400	WELL	PR	05/06/2010	GW	045-14960	SCHOOL HOUSE POINT OM 08A A21 696	PR
293401	WELL	PR	05/28/2015	OW	045-14961	SCHOOL HOUSE POINT OM13B A21 696	PR
293402	WELL	PR	05/29/2015	GW	045-14962	SCHOOL HOUSE POINT OM13C A21 696	PR

**General Comment:**

COGCC Inspection Report Summary  
On Tuesday 10/20/2020, I, Inspector Mike Longworth, conducted a inspection at (Operator Name) (Location Name), at BERRY PETROLEUM COMPANY LLC, SCHOOL HOUSE POINT OM A21 696, Location ID: 335516  
During this inspection the following possible compliance issues were observed:  
Fluid leaking from wheel valve on OM1A A21 696 annulus.  
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d..  
24 hours to fix the leak or isolate leak.  
CA Date 10/21/2020  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type:	Horizontal Heated Separator	# 8	corrective date
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical containers		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLs	PBV STEEL		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	293395	Type:	WELL	API Number:	045-14955	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well. Fluid leaking from wheel valve on OM1A A21 696 annulus.							Date:	10/21/2020
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 24 hours to fix the leak or isolate leak.							Date:	
Facility ID:	293398	Type:	WELL	API Number:	045-14958	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	293399	Type:	WELL	API Number:	045-14959	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	293400	Type:	WELL	API Number:	045-14960	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	293401	Type:	WELL	API Number:	045-14961	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	293402	Type:	WELL	API Number:	045-14962	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass					
		Culverts	Pass			
Gravel	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402515129	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274240">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274240</a>
701100618	Inspection 701100616 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274237">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274237</a>