

Location

Lease Road:			
	Type Access		
	comment: well is in a planted field		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
	Comment: adequate, form 10 Doc # 402476685 was submitted on 9-30-20 and is in process		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:		
	Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type WELLHEAD		
	Comment: fabricated steel pipe		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
	Comment: automation		
Corrective Action:			Date:
Type: Flow Line	# 3		
	Comment:		
Corrective Action:			Date:
Type: Bradenhead	# 1		
	Comment: appears to be plumbed to surface		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
	Comment:		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
	Comment:		
Corrective Action:			Date:

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	75 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:	shares containment with crude tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241320 Type: WELL API Number: 123-09109 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 11/18/2020 at approximately 1400 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman/Peterson Energy Operating Inc.location: Rasmussen 2 at API #05-123-09109 in Weld County Colorado. While there, I observed wellsite,PR at time of inspection. Form 10 Doc # 402476685 was submitted on 9-30-20 and is in process. Follow up to Doc # 699302573.</p> <p style="text-align: right;">This inspection is for this wellsite only, TB was inspected with Doc #699302567. During this inspection the following possible compliance issue has been addressed: 603.f housekeeping: weeds overgrown along access and around wellsite have been cut and removed. See attached photos. Location: dry, Weather: clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	11/18/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302990	location pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293853