

Inspection Photos

API: 071-07414

Operator: TIMBER CREEK OPERATING
OGRIS OPERATING LLC

Inspection Date: 11/19/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 11/19/2020

Inspection Photos



Photo 1. Stormwater is not being diverted toward the culvert which is causing erosion further down the road. Culverts need to be maintained for stormwater diversion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 11/19/2020

Inspection Photos



Photo 2. There is vehicle rutting occurring along the road which will only worsen if not repaired. The roads need to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 11/19/2020

Inspection Photos



Photo 3. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07414 | Date: 11/19/2020