

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/03/2020

Submitted Date:

12/04/2020

Document Number:

696302720

FIELD INSPECTION FORM

Loc ID 438056 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 20 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438057	WELL	PR	11/30/2014	OW	123-39858	State Seventy Holes A-E-6HNB	PR
438058	WELL	PR	11/27/2014	OW	123-39859	State Seventy Holes A11-E14-6HNC	PR
438059	WELL	PR	12/07/2014	OW	123-39860	State Seventy Holes 11-14-6HNB	PR
438060	WELL	PR	11/16/2014	OW	123-39861	State Seventy Holes F11-J14-6HNC	PR
438061	WELL	PR	12/06/2014	OW	123-39862	State Seventy Holes F-J-6HNB	PR

General Comment:

[This is a Follow-Up Inspection to FIR 696300934 dated 12.02.2019](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate (x5)		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Downhole Tools at the North end of Wellheads, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	01/04/2021
Type	STORAGE OF SUPL		
Comment:	Unused Secondary Containment in SW corner of Location. IF still in use - Wildlife netting is in Disrepair and Oily Waste is in Containment. See photos		
Corrective Action:	Comply with Rule 603.f. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e." Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 324 A.s	Date:	01/04/2021
Type	OTHER		
Comment:	Stained Soil at Rack (Where Compressor was removed) See photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."	Date:	12/21/2020
Type	OTHER		
Comment:	Stained Soil at F11-J14-6 HNC and A-E-6 HNB Wellheads, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."	Date:	12/21/2020

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Bird Protectors	# 9				
Gas Meter Run	# 10				
Horizontal Heated Separator	# 5				
Plunger Lift	# 5				
Emission Control Device	# 4				
Bradenhead	# 5	Appear to be plumbed to surface			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	60 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	500 BBLs	STEEL AST		40.346350,-104.371900
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities									
Facility ID:	438057	Type:	WELL	API Number:	123-39858	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	438058	Type:	WELL	API Number:	123-39859	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	438059	Type:	WELL	API Number:	123-39860	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	438060	Type:	WELL	API Number:	123-39861	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	438061	Type:	WELL	API Number:	123-39862	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Follow-Up Inspection. All Risers are now marked. Stained Soil at F11-J14-6 HNC and A-E-6 HNB Wellheads. Stained Soil at Rack. Unused Secondary Containment in SW Corner of Location. Unused Downhole Tools at North end of Wellheads.	petrie	12/04/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402546912	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5303468
696302721	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5303467