

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/21/2020

Submitted Date:

12/21/2020

Document Number:

700702048

FIELD INSPECTION FORM

Loc ID 335227 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: GRIZZLY OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211169	WELL	PR	06/24/1995	GW	045-06928	BROOME 1	PR
275528	WELL	PR	08/04/2009	GW	045-10341	GGU BROOME 43A-30-691	PR
275529	WELL	PR	07/01/2020	GW	045-10342	GGU BROOME 44C-30-691	PR
275530	WELL	PR	08/04/2009	GW	045-10343	GGU BROOME 44A-30-691	PR
275531	WELL	PR	08/23/2010	GW	045-10344	GGU BROOME 34C-30-691	PR

General Comment:

COGCC Inspection Report Summary
On Monday 12/21/20 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Broome 1, at Location # 335227 in Garfield county Colorado.
While there, I observed normal production operations. All meters have been calibrated on location within the past year. Limited storm water inspection due to snow.
During this inspection the following possible compliance issues were observed:

- Location shows signs of lack of stabilization BMP's in some areas (riiling is present) on cut slope behind tank battery
- No evidence of tracking control BMP's
- Tank sign needs maintenance
- Unused equipment at well heads(solar panel and injection pump)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	snow covered		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	• Tank sign needs maintenance		
Corrective Action:	Repair signage		Date: 01/21/2021
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	• Unused equipment/debris at well heads(solar panel and injection pump)		
Corrective Action:	remive unused equipment/debris		Date: 01/21/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 5		
Comment:	Braden heads have a port for manual gauge monitoring		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	200 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>211169</u>	Type:	<u>WELL</u>	API Number:	<u>045-06928</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>275528</u>	Type:	<u>WELL</u>	API Number:	<u>045-10341</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>275529</u>	Type:	<u>WELL</u>	API Number:	<u>045-10342</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>275530</u>	Type:	<u>WELL</u>	API Number:	<u>045-10343</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>275531</u>	Type:	<u>WELL</u>	API Number:	<u>045-10344</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Culverts		Ditches				
Berms		Culverts				

Comment: Limited storm water inspection due to snow.
 • Location shows signs of lack of stabilization BMP's in some areas (riiling is present) on cut slope behind tank battery
 • No evidence of tracking control BMP's

Corrective Action: Maintain BMP's
 Provide proof of tracking control BMP's

Date: 01/21/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402558612	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314574
700702053	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5314569