

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/22/2020

Submitted Date:

12/30/2020

Document Number:

700404722

**FIELD INSPECTION FORM**

Loc ID 315483 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Freeman, Kris	254-727-0435	kfreeman@31operating.com	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230909	WELL	SI	05/01/2020	GW	103-08578	CONTINENTAL 3-16	SI

**General Comment:**

- A routine inspection identified the following compliance issues:
- 1) Report past due monthly operations on Form 7. Complete by 7-15-2020.
  - 2) Provide bradenhead access. Photo 1. Complete by 2-1-2021.
  - 3) Calibrate gas meter. Photo 5. Complete by 2-1-2021.
  - 4) Have an emergency phone number that can be reached at all times. Complete by 1-1-2021.

This is a summary of inspection report 700404722.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment: Emergency phone, 800-209-9762, was called on 12-22-2020 @ 18:12. No one answered and no message service was available.

Corrective Action: Have an emergency phone number that can be reached at all times.

Date: 01/01/2021

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:			Date:

**Equipment:**

Type			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Most recent meter calibration in June 2017.		
Corrective Action:	<span style="color: red;">Meters need calibrated annually.</span>		Date: 02/01/2021
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		

Comment:	Bradenhead access is not present.		
Corrective Action:	Provide bradenhead access with appropriate fittings to allow determination of pressure and fluid flow.	Date:	02/01/2021

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 230909 Type: WELL API Number: 103-08578 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations. Last recorded production April 2020.  
No audible gas flow at well or meter building. Values from well head tubing to meter building appeared to be open. Tubing pressure 300 psi. Casing pressure 35 psi.

Corrective Action: **Submit required Form 7(s) to COGCC.** Date: 07/15/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Wildlife    Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:    Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402564023	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319314">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319314</a>
700404724	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319300">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5319300</a>