

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2021

Submitted Date:

01/04/2021

Document Number:

699502103

FIELD INSPECTION FORMLoc ID 320519 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10454

Name of Operator: PETROSHARE CORPORATION

Address: 9635 MAROON CIRCLE #400

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
GRIMES, MEGHAN		mgrimes@petrosharecorp.com	Principal Agent
Canfield, Chris		chris.canfield@state.co.us	
, COGCC		conor.pesicka@state.co.us	
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	Production Ops Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274769	WELL	PR	04/01/2020	GW	001-09524	CHAVEZ 7-17	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil near wellhead, pump house see pic 1,3		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	02/04/2021
Type	OTHER		
Comment:	Weeds, trash, unused equipment on location see pic 1,2,3,4,5,6		
Corrective Action:	Comply with 603 f.	Date:	02/04/2021
Type	OTHER		
Comment:	No BMP under chemical tank in pump house, small leak on ground. see pic 3,4		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.	Date:	02/04/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	6' chain link with barb wire / 4' barb wire around pump jack		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas motor		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	310 BBL				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 274769 Type: WELL API Number: 001-09524 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Annual bradenhead test is not current. Contact COGCC engineering.01/14/2021Corrective Action: Comply with 341 c.

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 1/4/21 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Chavez 7-17</p> <p>Company Name- Petroshare Corporation</p> <p>API- 05-001-09524</p> <p>In Adams County Colorado.</p> <p>While there, I observed producing well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil near wellhead, pump house see pic 1,3</p> <p>Properly treat or dispose of oily waste in accordance with 907.e.2/4/21</p> <p>Weeds, trash, unused equipment on location see pic 1,2,3,4,5,6</p> <p>Comply with 603 f. 2/4/21</p> <p>No BMP under chemical tank in pump house, small leak on ground. see pic 3,4</p> <p>Install or repair required BMPs per Rule 1002.f. 2/4/20</p> <p>Annual bradenhead test is not current. Contact COGCC engineering.</p> <p>Comply with 341 c 1/14/20</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection weather conditions were sunny, cold, recent snow.</p> <p>This is a summary of inspection report.</p>	medinaj	01/04/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402565835	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321341
699502104	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321334