

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/04/2021

Submitted Date:

01/04/2021

Document Number:

699502105

**FIELD INSPECTION FORM**
 Loc ID 319949 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10694

Name of Operator: PROVIDENCE OPERATING LLC DBA POCO

Address: 16400 DALLAS PARKWAY SUITE 400

City: DALLAS State: TX Zip: 75428

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Devin		dbrown@providence-energy.com	
Grimes, Meghan		mgrimes@providence-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201976	WELL	PR	06/01/2018	GW	001-07380	CHAMPLIN 78 AMOCO C 1	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: 4' barb wire

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: Automation

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		,	
Comment: 75 BBL						
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: shares containment with oil tank				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 201976 Type: WELL API Number: 001-07380 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Annual bradenhead test is not current. Contact COGCC engineering. Bradenhead test notice for 10/16/20 however no bradenhead test is on file.

01/14/2021Corrective Action: Comply with 341 c

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 1/4/21 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Champlin 78 Amoco C 1</p> <p>Company Name- POCO</p> <p>API- 05-001-07380</p> <p>In Adams County Colorado.</p> <p>While there, I observed producing well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Annual bradenhead test is not current. Contact COGCC engineering. Bradenhead test notice for 10/16/20 however no bradenhead test is on file.</p> <p>Comply with 341 c 1/14/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection weather conditions were sunny, cold, recent snow.</p> <p>This is a summary of inspection report.</p>	medinaj	01/04/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402565836	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321342">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321342</a>
699502106	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321335">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321335</a>