

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2021

Submitted Date:

01/04/2021

Document Number:

699502107

FIELD INSPECTION FORMLoc ID 319896 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #225

City: AURORA State: CO Zip: 80016

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Espinosa, Bill		billespinosa30@yahoo.com	
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201803	WELL	SI	06/01/2018	OW	001-07207	CHAMPLIN 78 AMOCO B 1	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds uncontrolled on location see pic 1,3,4,5,6,7		
Corrective Action:	Comply with 603 f	Date:	01/14/2021
Type	OTHER		
Comment:	stained soil around pump jack see pic 3,4,5,6,7		
Corrective Action:	"Properly treat or dispose of oily waste in accordance with 907.e	Date:	02/04/2021
Type	OTHER		
Comment:	no BMP under chemical tanks see pic 4,5,6,7		
Corrective Action:	Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2)B	Date:	01/14/2021
Type	OTHER		
Comment:	Well has been shut in since 6/1/2018 and needs a mechanical integrity test to ensure wellbore integrity. Contact COGCC engineering		
Corrective Action:	No current MIT on record or delinquent as required by Rule 326	Date:	01/04/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 201803 Type: WELL API Number: 001-07207 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: no MIT on record

Corrective Action: Comply with 326

Date: 01/04/2021

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 1/4/21 at approximately 1300 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Champlin 78 Amoco B 1</p> <p>Company Name- Renegade oil and gas</p> <p>API- 05-001-07207</p> <p>In Adams County Colorado.</p> <p>While there, I observed producing well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds uncontrolled on location see pic 1,3,4,5,6,7</p> <p>Comply with 603 f 1/14/21</p> <p>stained soil around pump jack see pic 3,4,5,6,7</p> <p>"Properly treat or dispose of oily waste in accordance with 907.e2/4/21</p> <p>no BMP under chemical tanks see pic 4,5,6,7</p> <p>Install adequate BMB for storage of materials that could result in the discharges causing pollution of surface waters per rule 1002 f (2)B 1/14/21</p> <p>Well has been shut in since 6/1/2018 and needs a mechanical integrity test to ensure wellbore integrity. Contact COGCC engineering</p> <p>No current MIT on record or delinquent as required by Rule 326 1/4/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection weather conditions were sunny, cold, recent snow.</p> <p>This is a summary of inspection report.</p>	medinaj	01/04/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402565837	INSPECTION SUBMITTED	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321343
699502108	pics	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321336