



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Ancillary equipment	# 1			
Comment:	Electric			
Corrective Action:				Date:
Type: Prime Mover	# 20			
Comment:	Electric motor			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240091 Type: WELL API Number: 123-07879 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Annual bradenhead is not current. Contact COGCC engineering.

01/08/2021

Corrective Action: Comply with 341 c

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 12/29/20 at approximately 1330 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Heit Antone C B 1                      Company Name- KPK                      API- 05-123-07879                      In Weld County Colorado.                      While there, I observed Producing well                      During this inspection the following possible compliance issues were observed:                      Annual bradenhead test is not current. Contact COGCC engineering.                      Comply with 341 c 1/8/21                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      At time of inspection weather conditions were cold, calm, recent snow.                      This is a summary of inspection report.</p>	medinaj	12/29/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402562370	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317817">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317817</a>
699502080	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317799">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5317799</a>