

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/11/2021

Submitted Date:

01/12/2021

Document Number:

700404936

**FIELD INSPECTION FORM**

Loc ID 465575 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 6720  
Name of Operator: ROBERT L BAYLESS PRODUCER LLC  
Address: 621 17TH ST STE 2300  
City: DENVER State: CO Zip: 80293

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465574	WELL	DG	08/09/2019		103-12363	Weaver Ridge 14-11H	DG
465576	WELL	XX	06/21/2019		103-12364	Weaver Ridge 14-14H1	ND
465577	WELL	DG	08/09/2019		103-12365	WEAVER RIDGE 14-14H2	DG

**General Comment:**

A follow up inspection of documents  
1) 700403665 dated 9-29-2020.  
2) 700404575 dated 12-14-2020.

The following compliance issues are uncompleted:

1) Well head signs were added at the location entrance before 12-14-202. The signs need moved to their individual well. A sign for Weaver Ridge 14-14H1 (05-103-12364) was added, but the well hasn't been drilled. A sign for Weaver Ridge 14-14H2 (05-103-12365) is missing. Photo 2 & 3. Complete by 12-1-2020.

This is a summary of inspection report 700404936.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well head signs were added at the location entrance. The signs need moved to their individual well. A sign for Weaver Ridge 14-14H1 (05-103-12364) was added, but the well hasn't been drilled. A sign for Weaver Ridge 14-14H2 (05-103-12365) is missing.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/01/2020

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 465574 Type: WELL API Number: 103-12363 Status: DG Insp. Status: DG

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: DG in August 2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 465576 Type: WELL API Number: 103-12364 Status: XX Insp. Status: ND

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Permit expires 6-20-2021.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 465577 Type: WELL API Number: 103-12365 Status: DG Insp. Status: DG

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: DG in August 2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: 7" of snow on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Drilling Pit                      Lined: YES                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type: Plastic                      Liner Condition: Adequate

Comment: Covered in snow.

Corrective Action

Date:

**Fencing:**

Fencing Type:                      Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:                      Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:                      Oil Accumulation:                      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402572695	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327817">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327817</a>
700404937	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327807">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327807</a>