

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2021

Submitted Date:

01/13/2021

Document Number:

701101022

FIELD INSPECTION FORM

Loc ID 334897 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259554	WELL	PR	03/19/2001	GW	045-07747	UNOCAL GM 242-1	PR
276584	WELL	PR	08/29/2005	GW	045-10484	WILLIAMS GM 511-1	PR
276585	WELL	PR	08/29/2005	GW	045-10483	WILLIAMS GM 412-1	PR

General Comment:

[COGCC Follow Inspection Report Summary](#)

I, Inspector Mike Longworth, conducted a follow up to 5/6/2020 inspection doc #689704660 at TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W 1NWNW, Location ID: 334897 in Garfield County, Colorado.

A follow up inspection was conducted on 11/18/2020 Inspection # 701100777

Corrective actions have not been addressed.

Unused Drilling Mud storage tanks have not been removed. Corrective action date 08/06/2020 has pasted.

Sediment from cut slope is stacked up against the north west mud tanks (8-300bbl) metal berm. Ditch on south west end on location has sediment build up and tire ruts. 2 dirt/rock stockpiles on south east of location at entrance with no bmps. Corrective action date 12/04/2020 has pasted.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Capacity units (bbl) have been added to tanks.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Drilling Mud storage tanks.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/06/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: <u>259554</u>	Type: <u>WELL</u>	API Number: <u>045-07747</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>276584</u>	Type: <u>WELL</u>	API Number: <u>045-10484</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	
Facility ID: <u>276585</u>	Type: <u>WELL</u>	API Number: <u>045-10483</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing well</u>		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Sediment from cut slope is stacked up against the north west mud tanks\(8-300bbl\) metal berm. Ditch on south west end on location has sediment build up and tire ruts. 2 dirt/rock stockpiles on south east of location at entrance with no bmps.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 12/04/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402574335	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5329430
701101023	Inspection 701101022 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5329420